

09/978,213

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,829,455 B2
DATED : December 7, 2004
INVENTOR(S) : Yasumoto et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 4,

Line 3, "photosensitive" should read -- photosensitive member --.

Column 5,

Line 43, "comprises" should read -- comprise --.

Column 9,

Line 57, "holes the" should read -- the holes --.

Column 12,

Line 18, "ments" should read -- ment --.

Column 19,


Line 18, "portion 10" should read -- portion 10 --.

Line 33, "driving system" should read -- driven system --.

Line 47, "this" should be deleted.

Signed and Sealed this

Seventeenth Day of May, 2005



JON W. DUDAS
Director of the United States Patent and Trademark Office